- 1. All wooden panels of shipped crates, which filled two skips, were dumped. The contents were arranged properly in the MICE Hall.
- 2. Some parts as shown in Photo 1, such as cooling hoses, bus bars for filament of tetrode power tube, anode chock coils and electric parts, should be attached to the HPD.



Photo 1: Parts for the HPD.

3. Spare triode power tube, support frame for TR-set and cavity bias power supply were moved from R40 to MICE Hall as shown in Photo 2. The power tube and the support frame, which are not used for the time being, must be arranged in MICE hall. The wooden crate of the bias power supply must be uncrated.



Photo 2: Spear triode power tube, support frame for TR-set and cavity bias power supply.

4. Before the wiring between HPD and equipments, the HPD on the rail should be arranged in MICE Hall properly.