		Mev												June																												
	40	May													Τ.															25												
	19	ZU T	21	ZZ Th		0 24	. (25 Z) 2	27 T	28 M	29 Th	30	0	1	0	Z N/I	J T	۱۸/	D Th	. '	о - «	60	Ö	9	T	11	Th	13	94	10)	0 I	т Т	10	19 Th	20	21	22	23	Z4 T	25
ISIS machine setup	IVI	-	VV	11	<u>' '</u>	00	2 (J 1V	+	<u>'</u>	vv	111	4	<u>ی</u>	2	<u> </u>	IVI		V V				Sa	3	101	-	VV	111	'	Je	. 3	11	/1	<u> </u>	VV	111	-	Sa	J	IVI	'	VV
ISIS user cycle													Ť												•	←						+				→						
Y Irie			\leftarrow												+					-	>																			=		
K Muto			\leftarrow				Ŧ		ŧ	+			1					\rightarrow																								
Availability for Experiments		Swe	ept n	nod	e, M	e, MCR R		:F contro		ol syster		em				No bias s		su	upply																							
Establish stable operation																																										
with swept mode																																										
◆stable operation in situ																																										
◆investigate waveform distortions																																										
◆stable operation controlled																																										
by MCR (AVC-, phase-loops ON)																																										
Investigate waveform distortions with no bias																																										_
Impedance Measurements							+		+	-																															\vdash	
by using liquid resistor														Ė	1																											
Breakout Box at SP6																																										
Cabling to SP6													H																											_		
◆lay cables																																										
◆cable terminations and check																																										
																																									шJ	