

## Weekly Progress Report

WPR011  
OKI Toshiyuki  
2004/08/13

Some parts, such as cooling hoses, bus bars for filament of tetrode power tube, anode chock coils and electric parts, were attached to the HPD as shown in Photo 1. I readjusted a few part due to its wrong design. Although there was a problem in a space for E2V plate chalk coil, it was also attached.




Photo 1: HPD with some parts.